
PARTS BULLETIN

Original Issue Date: **10/02**
 Models: **40-99EOZ/33-80EFOZ**
 Market: **Marine Generator Sets**
 Subject: **Heat Exchanger Cover Change**

John Deere changed the design of the heat exchanger cover on engine models 4045 and 6068. The heat exchanger cover outlet changed from a 30° to a 90° angle. As a result, Kohler Power Systems changed a molded hose in the engine groups. A generator set serial number break was taken to identify the change.

Use the table below to determine the replacement heat exchanger cover and molded hose.

Please note this change in groups 16 and 105 of parts catalog TP-5738 P/C 40-150COZ/EOZ, 33-125CFOZ/EFOZ

Service Part Numbers

Model	Specification Number	Replacement Part Number			
		Serial Number Before 0741565		Serial Number 0741565 and After	
		Heat Exchanger Cover	Molded Hose	Heat Exchanger Cover	Molded Hose
40EOZ/33EFOZ	GM24463-GA1	352143	GM14373	GM26367	GM25430
	GM24463-GA2	352143	GM14373	GM26367	GM25430
50EOZ/40EFOZ	GM24463-GA3	352143	344663	GM26367	GM25435
	GM24463-GA4	352143	344663	GM26367	GM25435
65EOZ/55EFOZ	GM24463-GA5	352143	344663	GM26367	GM25435
	GM24463-GA6	352143	344663	GM26367	GM25435
80EOZ/70EFOZ	GM24463-GA7	352143	344663	GM26367	GM25435
	GM24463-GA8	352143	344663	GM26367	GM25435
99EOZ/80EFOZ	GM24463-GA9	352143	344663	GM26367	GM25435
	GM24463-GA10	352143	344663	GM26367	GM25435