

ISSUE DATE: **4/89** MODEL: **4CZ/6.5CZ--** SUBJECT: **Fuel Pump Part** NO.: **489**  
REVISION DATE: -- **Marine** **No. 249862**

In certain marine applications where long fuel line runs, additional fuel filters, or highly restrictive anti-siphon breaks exist, the current fuel pump may not perform properly. This circumstance applies to generator sets shipped from Kohler Co. prior to April 28, 1989. Units shipped after April 28, 1989 will have a new higher psi (pounds per square inch) pump as standard.

This higher psi fuel pump, part no. 249862, can be ordered from Generator Service Parts. A flat rate of one-half hour has been established for this change and normal warranty travel time applies. Submit a Warranty Claim (Form K-1500) referencing this Service Bulletin. This program will be honored through August 31, 1989.

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							

